SI-1000 Adapter Quick install

Direct connected
ethernet line

1 Connect AP Device,
To "TO AP" port,via a ethernet line.

Direct connected
ethernet line

2 Connect Computer,
To "LAN" port,via a ethernet line.

Cross connected
Serial line

RS-232

3 Connect RS232 Port to Computer.
Maybe a USB-RS232 Translater Device shall be used.

1 2 3 4 5 6 7 8
ON↓
ADD   CONF

4 Confirm the Switch key is like
this.

DC
48V

+48V PE GND
POWER

5 Connect Switch Power supply
(DC48V) to power port.

TRAFFIC SENSOR INTERFACE BOX

48V,12V,3.3V LED is lighting, Run LED is flashing.

6 Power on.The LED lamp should
light.